
Subject: D Drive Squeek Question

Posted by [cuda](#) on Thu, 23 May 2013 03:54:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

Message-ID:

Date: Wed, 18-Jul-84 09:58:05 EDT

Article-I.D.: ihuxf.2321

Posted: Wed Jul 18 09:58:05 1984

Date-Received: Thu, 19-Jul-84 03:15:06 EDT

Organization: AT&T Bell Labs, Naperville, IL

Lines: 50

I saw the article about lubing up the drive and was in a tinkering mood so I thought I'd give it a try. It does help the squeeking. I used some Gunslick which is a graphite lubricant. (K-MART ~ .75\$ in the sports section)

However, I had just finished the drive and my wife was helping clean up when she said " Oh, here you missed a part. " After I scooped my face off the floor I realized I hadn't even seen the part come off. So my question is, could someone verify/correct me on the order of assembly?

Here is the way I reassembled it.

C
